## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	180/400.ccls. and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:01
L2	1149	439/402,342,296.ccls.	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L3	183	"439".clas. and steering and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L4	445	l2 and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L5	1	3 and  4	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:28
L6	28	73/862.08,862.191,862.321,862.326.ccls. and solder \$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:41
L7	112	73/866.1.ccls. and (solder\$3 steering torque)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:48
L8	16	73/866.1.ccls. and (steering)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:49
L9	8	73/431.ccls. and (steering)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:49
L10	119	73/862.08,862.191,862.321,862.326.ccls. and steering	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:50
S75	1356	((wire adj harnes\$5) and solder\$3)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 16:25
S76	62	(solder\$3 same (wire lead line pin)).clm. and S75	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 16:25
S77	30	(solder\$3 same (wire lead line pin)).clm. and S75	US-PGPUB	OR	ON	2008/08/14 16:26
S78	15	(solder\$3 and (wire lead line pin) and (torsion torque) and (detect\$4 sens\$4 measur\$4 transduc\$4 meter\$3)).clm.	US-PGPUB	OR	ON	2008/08/14 16:53

		.,	,	***************************************	,		ŧ
970	11/	180/444 cde, and solder\$3	I IS POPI IR	OR	ON :	2008/08/14	ŧ
(O) 3	( ) <del></del>	TOO/ 444.CCIS. and Solder 45	(00-1 GI OD )	Ort	şOI V	2000/00/14	3
- 11	3		3		} :	10.50	ì.
- 33	: }	- X			:	10.00	١.

8/14/2008 6:38:23 PM

C:\ Documents and Settings\ ppatel2\ My Documents\ EAST\ Workspaces\ 11136588.wsp